

SVA1000X Firmware Revision History

Version	Revision
V6.3R2	Notice:
2025/3/18	This firmware must be upgraded from V3.2.2.4.0 or later. If your analyzer has an earlier version, please update to V3.2.2.4.0 first and then proceed to update to the latest version.
	 New Functionality: Add measurement related functions, including: APSK function, Marker Band function, MA Record function and 200 Hz EMI RBW (only SVA1075X). Add system related functions, including: local oscillator feedthrough self calibration, 10M out frequency accuracy Self-Calibration function and FTP function. Improvements: Optimize the auto-save function, add the auto-save switch and auto-save time function to Last Preset. Add SCPI command, you can use the pscpi command to set/query the reference clock source used by the machine. Improve the measurement function, including increasing the number of markers in VNA mode to 14; optimize the measurement accuracy of the channel power measurement mode to ensure higher measurement accuracy. Solved Issues: Fixed some known defects.
V3.2.2.6.2R5 2024/2/22	Notice: This firmware must be upgraded from V3.2.2.4.0 or later. If your analyzer has an earlier version, please update to V3.2.2.4.0 first and then proceed to update to the latest version. New Functionality: VNA mode Ecal add Ecal Check, S11 Ecal, S21 Ecal. Add SCPI Command for Ecal Check [:SENSe#]:CORRection:ECAL:CONFidence:CHECk. Add SCPI Command for PV test [:SENSe#]:CORRection:ECAL:S21:PVTest, [:SENSe#]:CORRection:ECAL:S21:PVTest
	 Improvements: Display the exit command in Remote Control mode interface. SA/EMI/MA mode saves the current trace when saving user configuration SA mode auto tune does not change the amplitude Unit and Scale Type (Log/Linear) EMI mode exports Freq Interpoaltion (Log/Linear) when saving Imt file, and import the configuration when recalling the Imt file.
	 Solved Issues: Resolve the error issue of the SA mode TG waveform at 1.158GHz-1.168GHz. Fix the problem of MA mode setting the SCPI command for filter type: DDEMod:FILTer:MEASurement setting root raised cosine and raised cosine failed.



Version	Revision
	• Fix the problem that when the EMI mode does not have touch screen function, it is impossible to pull down to see more measurement results
V3.2.2.6.2 2023/12/14	Notice: This firmware must be upgraded from V3.2.2.4.0 or later. If your analyzer has an earlier version, please update to V3.2.2.4.0 first and then proceed to update to the latest version.
	 New Functionality: Add Picture Viewer Add Open Source Acknowledge Add Remote Control Mode, when entering, the interface displays system time, limit status, system messages, etc., shielding UI refresh. SCPI: DISPlay:WINDow:ENABle ON OFF Save the configuration every 60 seconds, and load it when Power On is turned Last SA/VNA mode Limit Setup adds Fail to Save, which automatically saves screenshot and trace data when the Limit Test result is Fail. It can only be used when Fail to Stop is turned ON
	 Improvements: Preset optimization: When pressing the Preset button, it will first jump to the Preset menu instead of directly performing Preset; Touch Assist's Preset adds preset option Optimization System Info display content When taking screenshots, do not capture the message indicating successful screenshot Limit the length of numbers entered on the screen and keypad Add SCPI commands to read system messages:SYSTem:MESSage? Added screenshot function under the Help window Set the FFT menu to invalid when the SA mode cannot select FFT SA mode can open the Freq Counter for markers other than marker 1 The SA mode peak table displays the peak of the current trace The SA mode peak table displays the peak of the current trace, rather than the current marker's trace The dBc parameter range of the SA mode OBW is changed to negative numbers When Noise Marker is turned on in SA mode, set Detect Type to Average In SA/MA/EMI mode, Wait for Trigger is displayed only if Trigger is not triggered for 2 seconds. Add Display Line in SA/VNA/DTF/MA/EMI mode When using markers in SA/VNA/DTF/MA/EMI modes, display the marker info enlarged in the upper left corner of the screen SA/EMI mode display more information of limit fail and pass Return more marker information when using SCPI command :CALCulate#:MARKer#:Y? in SA mode



Version	Revision
	specifying time units
	Solved Issues:
	 Fix the problem of the inconsistency between the numerical accuracy displayed in SA mode Freq menu Ref Offset and the status bar on the left Fix the problem of Marker display unit error when Noise Marker is turned on in SA mode Fix the problem of the SCPI command TRACe#:MODE in the SA mode setting trace type, which causes a crash when the selected trace exceeds the range. Fix the problem of not adding Freq Offset to the marker x value in SA mode
	 Fix the problem of Correction errors when switching between X-Scale Lin and Log in SA mode Fix the problem of inconsistent units and settings for values obtained by SCPI
	 commands :DISPlay:WINDow:TRACe:Y:RLEVel? in SA/EMI mode Fix the problen where Sweep Time may be incorrect when set EqLPF to Auto in MA mode
V3.2.2.6.0R7	Notice:
2023/5/3	This firmware must be upgraded from V3.2.2.4.0 or later. If your analyzer has an earlier version, please update to V3.2.2.4.0 first and then proceed to update to the latest version.
	New Functionality:
	Add ECal in VNA mode
	 Add three new formats in VNA mode: Unwrap Phase/Real/Imaginary
	 Add Z Reflection in VNA mode
	 Add PM demodulation in MA mode
	 The time of analog demodulation in MA mode is adjustable
	Improvements:
	Add SCPI command in VNA mode:
	Set the format Unwrap Phase/Real/Imaginary:
	CALCulate#[:SELected]:FORMat adds three new parameters for UWPH/REAL/IMAG Set Z Reflection:
	CALCulate#:TRACe#:CONVersion:FUNCtion OFF/ZREFlection
	Get the marker y value for Phase format with unwrap phase value:
	CALCulate#:FSCan:MARKer#:Y?
	Add SCPI commands for Calibration:
	Select Open Calibration [:SENSe#]:CORRection:COLLect:METHod[:RESPonse]:OPEN
	Select Short Calibration [:SENSe#]:CORRection:COLLect:METHod[:RESPonse]:SHORt
	Select Enhance calibration [:SENSe#]:CORRection:COLLect:METHod:ENHAnced
	Select Through Calibration [:SENSe#]:CORRection:COLLect:METHod[:RESPonse]:THRU
	Select 1 Port Calibration[:SENSe#]:CORRection:COLLect:METHod:SOLT1
	Add SCPI commands in MA mode:
	Set the scan time: [:SENSe]:SWEep:TIME

Version	Revision
	Set the demodulation type: ADEMod:STYLe (new parameter is PM)
	Get AM parameters: FETCh:AM#?
	Get FM parameters: FETCh:FM#?
	Get PM parameters: FETCh:PM#?
	Add system SCPI command:
	*OPC for EMI mode
	Exit remote status: SYSTem: LOCal for all mode
	Solved Issues:
	• Fix the problem that the bandwidth of the emi filter in SA mode
	• Fix the problem that setting the TG Level in SA mode may cause TG to have no output
	 Fix the problem that the n dB Marker measurement results in SA mode are inconsistent with the OBW measurement results
	 Fix the problem that there is an invalid frequency menu in Harmonic in SA mode
	 Fix the problem that the SCPI command: READ:ADEMod? would return an invalid value
	when reading the analog demodulation measurement results in MA mode
	 Fix the abnormality of the first scan in EMI mode
	 Fix the problem that setting rbw may crash when qpd is not enabled in EMI mode
	• Fix an issue where 'micro' relative units represented by 'u' were not recognized when
	reading files
V3.2.2.5.1R1	Notice:
2022/5/10	This firmware must be upgraded from V3.2.2.4.0 or later. If your analyzer has an earlier
	version, please update to V3.2.2.4.0 first and then proceed to update to the latest version.
	Improvements:
	Optimize the Ref level and Att couple
	Add SCPI commands in MA Mode
	•READ:ADEMod:AVG?
	•[:SENSe]:ADEMod:FM:DEVI?
	•[:SENSe]:ADEMod:FM:DRIFt?
	•[:SENSe]:BWIDth[:RESolution]
	•[:SENSe]:BWIDth[:RESolution]?
	•[:SENSe]:BWIDth:EQLPf
	•[:SENSe]:BWIDth:EQLPf?
	•CALCulate:MARKer#:PTPeak
	Add Cable Atten to correct cable loss in DTF Mode
	Add .trc file in EMI Mode
	Add .lic file auto scan
	Solved Issues:
	• Fix pi/4 DPSK 和 pi/8 DPSK decode errors in MA mode
	• Fix calibration error when port extension on in VNA mode



Version	Revision
	Fix fft frequency error in narrow span in SA mode
	• Fix trace avg calculation error in SA mode
	• Fix the zero sweep type when fft in SA mode
V3.2.2.5.0R1	Notice:
2021/9/30	This firmware must be upgraded from V3.2.2.4.0 or later. If your analyzer has an earlier
	version, please update to V3.2.2.4.0 first and then proceed to update to the latest version.
	New Functionality:
	Add Ext Trigger Delay from 0-10 seconds in SA Mode
	• Add Limit in Log mag and Lin mag format; add calibration average; add s1p touchstone
	file save in VNA mode
	Improvements:
	 VNA sweep points up to 10001; Scale down to 0.001 in Smith chart;
	MA Filter type Nyquist change to Raised Cosine to align SCPI command; improve filter
	performance in low frequency
	EMI RBW/Step from 1 to 3
	Solved Issues:
	• SA fix the difference between marker and peak and marker style; Fix Center Freq error;
	Fix limit fail to stop error; Fix Auto frequency error; In normalization, auto re-normalized
	after any setting changes
	• VNA Phase error; STA file saving error; CSA file loading error; S21 calibration error;
	Enhanced calibration error
	 EMI frequency offset error; saving std lim path error
	 Web browser cannot change IP, and cannot login after changing password
V3.2.2.4.0R2	Notice:
2021/2/9	This firmware must be upgraded from V2.1.1.1.12a or later. If your SVA1000X has an earlier
	version, please update to V2.1.1.1.12a first and then proceed to update to the latest version.
	Fix the VNA option license error on some SVA1015 and SVA1075 units
V3.2.2.4.0	Notice:
2021/1/15	This firmware must be upgraded from V2.1.1.1.12a or later. If your SVA1000X has an earlier
	version, please update to V2.1.1.1.12a first and then proceed to update to the latest version.
	• Fix TG switch error at small RBW
	 Fix Help and Limit file lost when Factory reset Fix Auto open delay unit error in VNA mode
	 Fix Auto open delay unit error in VNA mode Fix CNR cale error when no peak found
	Fix CNR calc error when no peak found Fix CNR/requilt everyflow
	Fix OBW result overflow Fix Hermonia cele error at 100Hz BBW
	Fix Harmonic calc error at 100Hz RBW



Version	Revision
	Fix Reflection Open+Short calibration action
	 Fix spectrum amplitude error in DMA mode
	 Optimize EMI .csv file content to all signal list
	Optimize EMI peak search
	Optimize Auto cal process
	 Add Peak search to Spectrum in DMA mode
	This version con not be rolled back
V3.2.2.3.3R1	Notice:
2020/12/01	This firmware must be upgraded from V2.1.1.1.12a or later. If your SVA1000X has an earlier
	version, please update to V2.1.1.1.12a first and then proceed to update to the latest version.
	New Functionality:
	Add EMI filter in SA for EMI option
	Solved Issues:
	Optimize the TG flatness and control procedure
	Optimize Help
	• Fix Correction, .csv file, add peak numbers to 20 in EMI mode
	• Fix ADC overload warning error, and time unit error in Calibration in VNA Mode
	Fix amplitude error in DMA Mode
	Fix upgrade failure issue
V3.2.2.3.2	Notice:
2020/09/09	This firmware must be upgraded from V2.1.1.1.12a or later. If your SVA1000X has an earlier
	version, please update to V2.1.1.1.12a first and then proceed to update to the latest version.
	New Eurotionality:
	 Add user defined VNA calibration kits
	Add User defined viva calibration kits Add VNA 0 span calibration
	Solved Issues:
	 Fix avg power bug in EMI Mode
	 Fix amplitude bug in AMA Mode
	 Fix peak search bug in SCPI command
V2.2.1.2.8	Notice:
2020/07/20	This firmware must be upgraded from V2.1.1.1.12a or later. If your SVA1000X has an earlier
	version, please update to V2.1.1.1.12a first and then proceed to update to the latest version.
	New Functionality:
	Update EMI option to a new EMI measurement mode
	Added more VNA calibration kits with N/3.5mm type connectors to 4.5G/9.0GHz
	• Added *.CSA file type to store instrument setup and calibration data in one file for easy



Version	Revision
	 recall and use of a saved state. Update user calibration data format. CAUTION: User calibration data taken with previous firmware revisions will no longer be compatible with the instrument after upgrading to V2.8. You will have to store new user calibration files if you update the instrument. VNA Port 1 output power and Port2 input Att adjustable Improvements: Improve TG output harmonic performance Update Help file
	 Solved Issues: Fix some ADC overload warning Fix Ch Power calculation bug in small span
V2.2.1.2.7 2020/05/12	Notice: This firmware must be upgraded from V2.1.1.1.12a or later. If your SVA1000X has an earlier version, please update to V2.1.1.1.12a first and then proceed to update to the latest version. New Functionality: Add Limit mask offset in SA mode Frequency LOG scale in VNA mode Add OPEN, SHOT, enhanced response in VNA mode Add 85033D/E Cal kit in VNA mode Save/recall .cal file in VNA mode Port 1 power (TG) adjustable in VNA mode Zero span in VNA mode Improvements: Smooth the glitch in Phase format in VNA mode Fixed AM and FM symbol rate error, Lpf coefficient error, in AMA mode Fixed Filter bandwidth error in DMA mode Fixed Filter bandwidth error in SA mode Fixed Harmonic error in SA mode Fixed Harmonic error in SA mode
V2.2.1.2.5 2019/11/11	Notice: This firmware must be upgraded from V2.1.1.1.12a or later. If your SVA1000X has an earlier version, please update to V2.1.1.1.12a first and then proceed to update to the latest version. Improvements:



Version	Revision
	 Optimize trace, marker, signal track, TG normalization in SA Mode
	 Optimize calibration flow, calibration algorithm and sweep speed in VNA Mode
	Optimize web server UI
	Solved Issues:
	 Fixed video trigger fail, errors in Harmonic measurement in SA Mode
	 Fixed admittance error, port extensions error in VNA Mode
	• Fixed spectrum amplitude error, meas error, waveform discontinue in MA Mode
	Fixed English help, system message
V2.2.1.2.2	Notice:
2019/8/1	This firmware must be upgraded from V2.1.1.1.12a or later. If your SVA1000X has an earlier
	version, please update to V2.1.1.1.12a first and then proceed to update to the latest version.
	New Functionality:
	 Add a spectrum view, marker for MA Mode
	Add mode couple for center frequency
	Add system message
	Improvements:
	Optimize .sta file, trace interpolation for VNA Mode
	Optimize PSK/QAM clock sync ability for MA Mode
	Solved Issues:
	• Fixed AVG, Math bug for VNA Mode
	• Fixed Date&Time set bug
V2.2.1.2.1	Notice:
2019/6/1	This firmware must be upgraded from V2.1.1.1.12a or later. If your SVA1000X has an earlier
	version, please update to V2.1.1.1.12a first and then proceed to update to the latest version.
	New Functionality:
	Add CNR, Harmonic measurement in AMK options for SA Mode
	• Add port extensions, user cal kit, new marker functions, correction switch, multi-traces
	and multi-format overlay display for VNA Mode
	• Extend xQAM, MSK, xPSK modulation analysis in DMA option for MA Mode
	Add new marker functions, multi-traces and multi-format overlay display for MA Mode
	Add SCPI commands for VNA and MA Modes
	 Add some system functions: Screen Annotation in Display menu, FTP server for file transfer
	Improvements:
	 Optimize UI, refresh and response for all Modes



Version	Revision
	 Optimize SCPI commands for basic control, such as INIT, *OPC?, *ESR, Abort, etc. Optimize Log scale axes, Peak search, Auto tune, TG normalization for SA Mode Optimize S11 and S21 simultaneous measurement, calibration control, trace control and auto scale for VNA Mode Optimize some system functions: Power Saving, IP config Solved Issues: Fixed OBW Transmit Freq Error Fixed bugs during Mode switch
V2.1.1.1.13	Now Eurotionality:
2018/11/1	 New Functionality: Screen saver for power saving
2010/11/1	 VNC View only for web server
	 VNA: .csv file for each format, Expand Phase for marker
	Improvements:
	• VNA: Auto Scale, min Scale to 0.1 dB
	DTF: logistic scale for RL display
	Solved Issues:
	Invalid Demod time in FM
	Scale in TG
	Wrong units in Markers and peaks
	Boot or Mode start lock up
	Udisk display wrong files
	SCPI command incompatible
	Min span to 10kHz in AMK power measurement
V2.1.1.1.12a	1. Spectrum Analysis mode: Improved the stability of sweep and interface.
2018/8/8	 VNA mode: fasten the VNA sweep speed; expand the minimum span from 10M to 10 kHz.
	3. Modulation Analysis mode: add trigger, optimize the modulation analysis algorithm.
	4. Add user port number selection for web server.