Revision History

Date	Version	Revision
2024/06/25	1.1.20R7	1. Standard software functions of FG and LA.
2024/02/22	1.1.20R6	 Fixed the bug: The average of measurement is mistake for 35M points
		 Optimized the time of auto-setup
2020/06/28	1.1.19R5	1. Added support for the SAG10211 USB Isolated AWG Module Hardware
		2. Fixed the bug: Sometimes PNSU command returns invalid value (Need referring to the latest Program Guide)
		3. Added 9 data bits for UART decoding
		 Fixed the bug of UART decoder with some special settings
		5. Increased baud rate of UART trigger from 5 Mbps to 20 Mbps
		6. Fixed the bug: The command 'WF? DAT2' returns error length of waveform when digital is enable
		 Fixed the bug: CSV file of waveform has no indication of the trigger point in the data
		 Fixed the bug: After repowering all FFT markers are on just one peak
		 Fixed the bug: After repowering, signal level of CAN trigger can't be recalled
		10. Fixed a few SCPI Commands errors:
		MATH: CURSOR_VALUE?
		C3:INVERT_SET? is missing
		HISTORY_LIST? is missing
		DIGITAL:LOW8_SWICHT, typo in name
		C5:COUPLING? typo in name
		11. Fixed the Bode Plot bug: Sometime there isn't enough delay after the scope switches timebase values before it
		tries to take a measurement 12. Fixed the bug : Matlab can' t import 14 M Matlab waveform files
		13. Fixed the bug: 'WF?' command ignores the length set by 'WFSU' for digital
2019/08/21	1.1.19R2	 Optimized communication between SDS2000X-E and SLA1016. This revision (and higher) requires the SLA1016 MUST be upgraded to 8.1.16 (or higher) first. Please take a look at 'Compatibility with SLA1016' at the end of the release notes.

SIGLENT 常和 SDS2000X-E Firmware Revision History And Update Instructions

Version	Revision
	2. Optimized Bode Plot: Accuracy and Sensitiv
	Improvement, New Vari-level Mode for Testing Lo
	Response, Miscellaneous Function and UI Improvemen
	3. Optimized FFT UI: Added Peaks, Markers, and sear
	within FFT.
	4. Optimize self-calibration for channels.
	5. Optimized accessing USB drive so that when a USB drive
	is moved to a computer, Windows will not prompt
	restoration of the USB drive.
	6. Optimize WIFI connection: 63 characters can now be us
	for a WPA2 PSK key.
	 Added parity options of MARK/SPACE for UART of 9- Decode.
	 Optimized behavior of the cursors (x-axis): Added mode that the cursors remain at the set position on t waveform when changing time base.
	 Added automatic reset to 0 for sample count for statist after any timebase or voltage range changes.
	 Fixed the bug: The audible beeper activation would affect the voltage waveform displayed for CH2.
	11. Fixed the bug of ROV measurement.
	12. Fixed the bug: Normal trigger can show more-than-o
	trigger event on the display at one time.
	13. Fixed the bug: Erratic triggering, randomly jumpi
	between the first and the second edge of a signal.
	14. Fixe the bug: The acquire time of history is reset to zee if the time reach 1 hour and 11 minutes. The delta time also wrong if the period is longer than 1 hour and minutes.
	 Fixed The SPI triggering issue: the 16-bit trigger would work for a gap >360 ns between the two 8-bit packets
	 16. Fixed the bug: Save/Recall setup of trigger and sca issue. (SalesForce ID: P-00199) (SalesForce ID: P-00200)
	 (SalesForce ID: P-00199) (SalesForce ID: P-00200) 17. Fixed the bug: Reading cursors by SCPI is not accurate (SalesForce ID: P-00201)
	 Fixed the bug: In fine adjust mode, some scale such 302 mV/DIV is in the wrong position.
	19. Fixed the bug: LIN decoder doesn't decode frames w
	zero-length response.
	20. Fixed the bug: If the Courser Offset is not a multiple
	zoom time base, the curser will be replaced wh zoomed.

SIGLENT開作 SDS2000X-E Firmware Revision History And Update Instructions

Date	Version	Revision
		 21. Fixed the bug: The measurements made with the cursor in Ref. Give wrong values for all the different probes of X1. 22. Fixed the bug: Measures fairs with GATE give completely random values in signals of low frequency.
2018/12/24	1.1.17R6	14. Fixed the bug: If the oscilloscope is switched off when the CH1 menu is active, it remains without a menu when switching on again.
2018/12/12	1.1.17R5	1. Initial formal release of SDS2000X-E

Compatibility between Versions

Source Version	Object Version	Compatibility
1.1.20R6	1.1.20R7	Yes
1.1.20R3	1.1.20R7	Yes
1.1.20	1.1.20R7	Yes
1.1.19R5	1.1.20R7	Yes
1.1.19R2	1.1.20R7	Yes
1.1.17R6	1.1.20R7	Yes
1.1.17R5	1.1.20R7	Yes

Compatibility with SLA1016

Source	Object	Compatibility
Version	Version	
8.1.16	1.1.20R7	Yes
8.1.16	1.1.20R6	Yes
8.1.16	1.1.20R3	Yes
8.1.16	1.1.20	Yes
8.1.16	1.1.19R5	Yes
8.1.11	1.1.19R5	No
8.1.9	1.1.19R5	No
8.1.8	1.1.19R5	No

Update instructions

• Very important!

Optimized communication between SDS2000X-E and SLA1016. If the SDS2000X-E will be upgraded to 1.1.19R2 (or higher), the SLA1016 **MUST** be upgraded to 8.1.16 (or higher) first.

Important!

Because 1.1.19R2 optimized self-calibration for each channel. Please perform a self-calibration if the machine is updated to 1.1.19R2 (or higher).