

## Revision History

Version	Revision
V1.1.1.2.4 2020/11/12	<ol style="list-style-type: none"><li>1. Fix: The UI was not updated in time when the power meter was pulled out.</li><li>2. Fix: GPIB Address can not be changed.</li><li>3. Fix: The mouse is hidden under VNC.</li><li>4. Fix: Some wrong SCPI commands were executed.</li><li>5. Optimize function with OCXO module.</li><li>6. Optimize power meter function.</li></ol>
V1.1.1.2.2 2020/09/02	<ol style="list-style-type: none"><li>1. Fix: Some power meter related SCPI commands do not work</li><li>2. Fix: UI cannot be set without IQ board</li></ol>
V1.1.1.2.1 2020/08/17	<ol style="list-style-type: none"><li>1. Optimize an overshoot signal generated when ALC is off.</li><li>2. Changing the offset range of multicarrier.</li><li>3. Optimizing the process of multicarrier generation.</li><li>4. Add a prompt box when using remote mode.</li><li>5. Use new license generation scheme</li></ol>
V1.1.1.1.9c 2020/06/18	<ol style="list-style-type: none"><li>1. Fix: There is a probability that white screen will appear after power on.</li><li>2. Fix: AWGN State no reset.</li><li>3. The IQ board detection only needs detection once.</li></ol>
V1.1.1.1.9a 2020/5/14	The first released