

SSA3000X-R Firmware Revision History

| Version | Revision |
|----------------------------|--|
| V3.2.2.4.0 2021/1/15 | <ul style="list-style-type: none"> • This version can not be rolled back • Fix TG switch error at small RBW • Fix Help and Limit file lost when Factory reset • Fix Auto open delay unit error in VNA mode • Fix CNR calc error when no peak found • Fix OBW result overflow • Fix Harmonic calc error at 100Hz RBW • Fix Reflection Open+Short calibration action • Fix spectrum amplitude error in DMA mode • Optimize EMI .csv file content to all signal list • Optimize EMI peak search • Optimize Auto cal process • Add Peak search to Spectrum in DMA mode |
| V3.2.2.3.3R1 2020/12/01 | <p>New Functionality:</p> <ul style="list-style-type: none"> • Add EMI filter in SA for EMI option <p>Solved Issues:</p> <ul style="list-style-type: none"> • Optimize the response in RTSA • Optimize the TG flatness and control procedure • Optimize Help • Fix Correction, .csv file, add peak numbers to 20 in EMI mode • Fix ADC overload warning error, and time unit error in Calibration in VNA Mode • Fix amplitude error in DMA Mode • Fix the frequency band downgrade to 3.2GHz on some units <p>Fix upgrade failure issue</p> |
| V3.2.2.3.2 2020/09/09 | <p>New Functionality:</p> <ul style="list-style-type: none"> • Add VNA and DTF mode • Update EMI option to a new EMI measurement mode <p>Solved Issues:</p> <ul style="list-style-type: none"> • Fix bug in Help File • Fix some ADC overload warning • Fix some PvT and Density marker bugs. • Fix Ch Power calculation bug in small span in SA Mode • Fix amplitude bug in AMA Mode • Fix peak search bug in SCPI command |

