

## Revision History

Date	Version	Revision
2019/4/16	1.1.1.19R1	1. The first software version.
2020/1/14	1.1.1.21	1. The software version adds socket functionality and support for EasySDL.
2021/5/20	1.1.1.21R2	1. Fix bug: DHCP turn to be ON state after send *RST command. 2. Some units will crash after run for some time.
2022/9/8	1.1.1.22	1.Modify the EEROM model software matching upgrade;
2023/3/10	1.1.1.22R1	1. Modify the BUG of the fan false trigger protection function;
2023/6/20	1.1.1.23R1	1. Added DCR measurement function.
2024/4/3	1. 1. 1. 23R2	1.NI-VISA cannot send instructions after installing the Keysight-VISA environment.
2024/12/26	1. 1. 1. 23R4	1.The strategy for controlling the fan is optimized.

## Compatibility between Versions

Source Version	Object Version	Compatibility
1.1.1.19R1		Yes
1.1.1.21		Yes
1.1.1.21R2		Yes
1.1.1.22		Yes
1.1.1.22R1		Yes
1.1.1.23R1		Yes
1.1.1.23R2		Yes
1.1.1.23R4		Yes

## Update instructions

- ◆ Very important!  
After the upgrade is complete, restart the machine.