

Revision History

Date	Version	Revision
2020/10/15	1.02.01.01.03R6	<ol style="list-style-type: none">1、 The buzzer abnormally sounds when the set value overranges2、 Change the limit of series voltage to 60V3、 fix a bug of recall function.
