

Revision History

| Date | Version | Revision |
|-----------|--------------|---|
| 2021/7/8 | 3.01.01.10 | <ol style="list-style-type: none">1. Add the scan card setup save&recall function.2. Optimize the slot time of the channel switching of scan card.3. Optimize flash R&W design.4. Fix some UI & SCPI bugs. |
| 2021/5 | 3.01.01.08R1 | <ol style="list-style-type: none">1. Fixed some crash fault about U disk save & recall.2. Fixed some bugs about "acquire" function.3. Improve the trend display function.4. Fixed some bugs about communication with easysdm |
| 2019/1/30 | 3.01.01.06R2 | <ol style="list-style-type: none">1. Add DHCP function to IP addressing2. Add Open Socket at LAN port 50253. Add over current protect function in a special case4. Fix a crash fault when restoring settings5. Modify the calibration arithmetic in 2-wire resistance measurement 10 MOhm range6. Add "ABORT BULK IN", "INITIATE CLEAR" features to remote SCPI commands |
| 2017/4/06 | 3.01.01.03 | <ol style="list-style-type: none">1. Add U disk recovery function2. Add the update of the calibration data function3. Fix the bug of a few abnormal DCV measurements when the input terminal is shorted4. Repair the external trigger problem5. Add the telnet SCPI function; port is 5024 Example: telnet 192.168.0.10 50246. FPGA optimization |