# Revision History

| Date | Version | Revision |
|------|---------|----------|
| 2022/10/20 | 6.01.01.25 | Compatible with new hardware |
| 2021/7/30 | 6.01.01.22 | Compatible with new hardware |
| 2019/9/20 | 6.01.01.21R2 | Optimize self-calibration for channels. |
| 2017/4/7 | 6.01.01.19 | 1. Repaired bug causing Math error when trace is stopped in dot display mode<br>2. Fixed 'add measurement' error in Polish language<br>3. Bug repaired when measuring frequency of 500 Hz, using alternate trigger, and a time base of greater than 1 ms/div |
| 2016/10/20 | 6.01.01.18 | 1. Fixed condition where wave trace departs from zero line while there is offset<br>2. Fixed bug: Sample rate of zoom changed after STOP in dot display mode<br>3. Fixed bug: All measurements on, select source on a disable channel. Reboot the Scope, then the software hangs on the boot screen<br>4. Adjusted keyboard scan method to optimize recognizing keyboard value<br>5. Modified BMP from 24bit to 16bit while save/get BMP form Scope |
| 2015/11/30 | 6.01.01.08 | The first formal release |

## Compatibility between Versions

| Source Version | Object Version | Compatibility |
|---|---|---|
| | | |
| | | |

## Update instructions

Before updating the ADS file, the ADS file need to be renamed and ensured that its name is less than 9 letters.