

Revision History

Date	Version	Revision
2021/1/07	3.01.01.08R1	<ol style="list-style-type: none">1. Fixed some crash faults about U disk Save &Recall.2. Fixed some bugs about “acquire” function.3. Improve the trend display function.4. Fixed some bugs about communication with EasyDMM
2020/1/18	3.01.01.07	<ol style="list-style-type: none">1. Add customer defined senior function2. Add PT1000 thermistor.3. Add buzzer volume control function.4. Added customer defined time base in the trend diagram5. Added recording measurement data to external U disk .6. Fix some bugs: change the text size in the Dual display, the screen saving setup will be lost after reboot, move the CSV save function from the utility page to acquire page.
2019/1/30	3.01.01.06R2	<ol style="list-style-type: none">1. Add DHCP function to IP addressing2. Add Open Socket at LAN port 50253. Add over current protect function in a special case4. Fix a crash fault when restoring settings5. Modify the calibration arithmetic in 2-wire resistance measurement 10 MOhm range6. Add “ABORT BULK IN” ,”INITIATE CLEAR” features to remote SCPI commands
2017/4/06	3.01.01.03	<ol style="list-style-type: none">1. Add U disk recovery function2. Add the update of the calibration data function3. Fix the bug of a few abnormal DCV measurements when the input terminal is shorted4. Repair the external trigger problem5. Add the telnet SCPI function; port is 5024 Example: telnet 192.168.0.10 50246. FPGA optimization