

## **Revise History**

Date	Version	Revision
3/10/2025	1.08.01.15R7	Solve the problem that the sync signal is
		output when the channel is not turned on
		2. After the sweep is completed, the output
		frequency is modified to stay at the initial
		frequency of the sweep.
2/22/2023	1.08.01.15R3	Fix the compatibility bug of Rev.E hardware,
		and generally do not need to upgrade.
8/5/2022	1.08.01.15R2	2. Fixed the bug that startup occasional failures
		3. Fixed the bug of burst sync output exception
		4. Fixed the bug that may not output when switch
		the waveform after the burst is turn off
12/3/2020	1.08.01.15	Supported to automatically enable the output
		after power-on: Utility   Output Setup   Power
		on State
		Compatible with Rev.E hardware
7/16/2019	1.08.01.13R9	Fixed the abnormal display issue during start-up on
		some units with previous releases. It is not
		necessary to update to this version if the unit has
		no such a problem.
8/30/2018	1.08.01.13R6	Fixed the incorrect sweep direction bug
		(2018/05/23-115276)
3/21/2018	1.08.01.13R5	It is strongly recommended to update to the latest
		release because in some previous release exists
		some serious bug which could cause the generator
		never startup
		<ol> <li>Supported system recovery from the U-disk</li> </ol>
		<ol><li>Supported Rev.C hardware with Over Voltage</li></ol>
		Protection
6/7/2016	1.08.01.12R2	Fixed several bugs
		<ul> <li>a) A bug in P12R1 which could cause the</li> </ul>
		update to fail
		b) Some typo in English help system
3/7/2016	1.08.01.12R1	Fixed several bugs
		<ul> <li>a) A bug in file system could cause the</li> </ul>
		generator never startup
		b) Can not wake up from screen saver from
		time to time
11/9/2015	1.08.01.11	<ol> <li>Re-open the self-calibration function</li> </ol>
		<ol><li>Fixed a bug which may cause the generator</li></ol>



Date	Version	Revision
		can not startup
		<ol><li>Fixed several other bugs</li></ol>