

Revision History

Date	Version	Revision
2021/9/22	5.01.01.07R1	<ol style="list-style-type: none">1. Add the customer sensor support.2. Optimize flash R&W design.3. Fix some UI & SCPI bugs
2021/2/5	5.01.01.06R1	<ol style="list-style-type: none">1. Fixed some unit faults in 06 version2. Fixed some bugs about communication with EasyDMM.
2021/1/8	5.01.01.06	<ol style="list-style-type: none">1. Fixed some crash fault about U disk save&recall.2. Fixed some bugs about “acquire” function.3. Improve the trend display function.4. Update the software platform code.
2019/4/23	5.01.01.05	<ol style="list-style-type: none">1. Change the size of text in dual display mode.2. Added customer defined time base in the trend diagram.3. Enhanced the volume of buzzer.4. Bug fix: The screen saving setup was lost after power cycle/reboot.5. Moved CSV file save function from the utility page to the acquire page.6. Added recording measurement data to external U disk.
2017/6/06	5.01.01.03	<ol style="list-style-type: none">1. Add U disk recovery function.2. Modify Hold function arithmetic.3. Add the telnet SCPI function; port is 50244. Example: telnet 192.168.0.10 5024