

## Revision History

Date	Version	Revision
2022/6/8	1.02.01.01.03R10	<ol style="list-style-type: none"><li>1. Add the OCP function (Long push the current button ('A') get into or exit OCP function)</li><li>2. Some improvements about the USB's stability.</li><li>3. Compatible new ADC</li></ol>
2020/10/15	1.02.01.01.03R6	<ol style="list-style-type: none"><li>1. The buzzer abnormally sounds when the set value overranges</li><li>2. Changed the limit of series voltage to 60V</li><li>3. Fixed a bug of recall function.</li></ol>